



CHECKMATE PRODUCTS cc

Reg No. 1987/011025/23
Vat No: 4700109962

1 PRINS STREET
BRITS INDUSTRIAL SITES
TEL: (012) 250-2320
FAX: (012) 250-3127
INT TEL. +27 12 250 2320
INT FAX. +27 12 250 3127

POSTAL ADDRESS:
PO BOX 631
0216 HARTBEEPOORT
SOUTH AFRICA

MANUFACTURERS OF STEEL AND FIBREGLASS COMPONENTS

25 November 2008

Goscor Power Products

P O Box 12174

CHLOORKOP

1624

Dear Pieter

Just a short note to thank you for the excellent service and products delivered over the past 21 years.

We started our business in 1987 building Go Karts & Mini Jeeps and your motors were the first to be fitted to our products and are still being used. As the eventual owners of our Go Karts are teenagers you can well imagine what hammering and misuse these products had to undergo. I can respectfully say that no SABS or equal test facility can really measure up to the wear and abuse of petrol powered products as that inflicted on your motors by teenagers.

Over the years a lot of Karts that came in for service and we found many with the governors tied out with wire to improve performance of the Kart. I explained to them this should not be done and as one client said: "Leave that governor out, it has been out for the past 4 years and the Kart still goes like hell."

I am glad to say that during the past 21 years we only had 1 motor returned under guarantee claim and your agent in Klerksdorp had it fixed and returned to the client the same day.

Most of the motors on the market was used by us at some stage or another, but we are proud to say the Robin is the toughest most reliable motor by far.

One kart went over a farm dam wall and landed in 2 meter water at full revs. They dried it up and no damage to the motor, only the kid's ego.

Another kid lost his oil filler plug and all the oil blew out the back of the kart. I can still recall the dad explaining the sudden silence of a Robin motor seizing up at full speed. He sent the kids all over the farm looking for the filler plug the next day. They found it, filled it with oil, dad pulled as hard as he could on the starter rope, it came loose and started on the same pull.

Unknown
Nov 26, '08, 11:06 AM
Added Text

Unknown
Nov 26, '08, 11:06 AM
Added Text

Unknown
Nov 26, '08, 11:06 AM
Added Text

Unknown
Nov 26, '08, 11:06 AM
Added Text

Unknown
Nov 26, '08, 11:06 AM
Added Text

Unknown
Nov 26, '08, 11:06 AM
Added Text

Two months later they came to buy new tyres and the motor was still going fine. That farmer said that after this experience he will never use any other motor than a Robin.

Thought I have to share this with you and congratulate your company on supplying the best motor on the market.

Thanks for the excellent service we received from you in the past 21 years and proud to be associated to Goscor.

FANIE & INA SCHOEMAN